

8 November 1956


MEMORANDUM FOR: Chief, Space Maintenance and Facilities Branch, OL
THROUGH : Chief, Administrative Staff, ORR
FROM : Chief, Industrial Division, ORR
SUBJECT : Electrical Installations and Other Repairs.

1. Electrical outlets are needed in the following rooms assigned to the Industrial Division:

1112 Q	1 Double Outlet
1116 Q	1 Double Outlet
1117 Q	2 Double Outlets
1019 Q	5 Double Outlets
1201 Q	1 Double Outlet
1208 Q	4 Double Outlets
1212 Q	2 Double Outlets
1216 Q	3 Double Outlets
1218 Q	1 Double Outlet


2. An electric fan should be mounted on the wall of Room 1019 Q.

3. Both air conditioners (1 Remington console and 1 Carrier console) in Room 1019 Q need repairs. One machine has a faulty plug or wall socket. The other machine has a faulty damper. Another air conditioner (Feddars, window-type) located in Room 1541 M is also in need of repairs (overhaul).

 25X1A9a

Distribution:

Orig. and 1 - Addressee
1 - Ch/St/A
2 - D/I

25X1A9a ORR/D/I:  2345 (8 November 1956)